Verification Report

No.: NGBEC26003735301 **Date:** Jun 08, 2026

Client Name: SOLENSO ELECTRONIC MATERIALS CO.,LTD.

Client Address: 4F.,NO.56,ZILI 5TH ST.,ZHONGLI DIST.,TAOYUAN CITY 320,TAIWAN,CHINA

Sample Name: Microinverter

Tested Basic Model No.: SG*

Tested Extended Model No.: SG1000、SG500

Client Ref. Information: SG400/SG450/SG800/SG900/SG1600/SG2000

The above sample(s) and information were provided by the client.

SGS Job No.: NBP26-003810

Sample Receiving Date: May 11, 2026

Verification Period: May 11, 2026 ~ Jun 05, 2026

Verification Requested: With reference to RoHS Directive (EU) 2015/863 amending 2011/65/EU.

Verification Method(s): Please refer to next page(s).

Verification Result(s): Please refer to next page(s).

Test Result Summary:

Test Items	Conclusion
EU RoHS Directive (EU) 2015/863 amending Annex II to Directive 2011/65/EU - Lead, Mercury, Cadmium, Hexavalent chromium, Polybrominated biphenyls (PBB), Polybrominated diphenyl ethers (PBDE), Bis(2-ethylhexyl) phthalate (DEHP), Butyl benzyl phthalate (BBP), Dibutyl phthalate (DBP) and Diisobutyl phthalate (DIBP)	Pass

Signed for and on behalf of
SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Hedy Hu
Approved Signatory


Scan to see the report

6D63136D


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，006幢5号楼4层2区，008幢7号楼1层6区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Photo of Submitted Sample



SG*




SG1000

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Member of the SGS Group (SGS SA)



SG500

Verification Method(s):

1. With reference to IEC 62321-2:2021, disassembly and disjointment were performed for the submitted samples.
2. With reference to IEC 62321-1:2013, tests were performed for the samples indicated by the photos in this report.
   (1) With reference to IEC 62321-3-1:2013, screening by EDXRF spectroscopy.
   (2) Wet chemical test method: With reference to IEC 62321-4:2013+A1:2017, IEC62321-5:2013, IEC 62321-7-1:2015, IEC 62321-7-2:2017, IEC 62321-12:2023, IEC 62321-6:2015 and IEC62321-8:2017 , analyzed by ICP-OES,UV-Vis and GC-MS.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab (Ningbo)

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Verification Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	NGB26-0037353-0001.C001	Silvery metal piece
SN2	A2	NGB26-0037353-0001.C002	Silvery metal
SN3	A3	NGB26-0037353-0001.C003	Black foam
SN4	A4	NGB26-0037353-0001.C004	Silvery metal base
SN5	A5	NGB26-0037353-0001.C005	Gray coating
SN6	A6	NGB26-0037353-0001.C006	Black plastic
SN7	A7	NGB26-0037353-0001.C007	Gray solid adhesive
SN8	A8	NGB26-0037353-0001.C008	Transparent yellow plastic adhesive tape
SN9	A9	NGB26-0037353-0001.C009	Black plastic shell
SN10	A10	NGB26-0037353-0001.C010	Golden metal
SN11	A11	NGB26-0037353-0001.C011	Black plastic
SN12	A12	NGB26-0037353-0001.C012	Black solid adhesive
SN13	A13	NGB26-0037353-0001.C013	Black plastic
SN14	A14	NGB26-0037353-0001.C014	Black plastic jacket
SN15	A15	NGB26-0037353-0001.C015	Golden metal
SN16	A16	NGB26-0037353-0001.C016	Rose red plastic jacket
SN17	A17	NGB26-0037353-0001.C017	Green plastic jacket
SN18	A18	NGB26-0037353-0001.C018	Black plastic jacket
SN19	A19	NGB26-0037353-0001.C019	Black plastic
SN20	A20	NGB26-0037353-0001.C020	White solid adhesive
SN21	A21	NGB26-0037353-0001.C021	Black plastic sheath
SN22	A22	NGB26-0037353-0001.C022	Semitransparent plastic jacket
SN23	A23	NGB26-0037353-0001.C023	Green PCB body
SN24	A24.1	NGB26-0037353-0001.C024.C001	Silvery metal soldering tin (A24 improved sample submitted by 2026-6-1)
SN25	A25	NGB26-0037353-0001.C025	Silvery metal spring
SN26	A26	NGB26-0037353-0001.C026	Silvery metal screw
SN27	A27	NGB26-0037353-0001.C027	White plastic
SN28	A28	NGB26-0037353-0001.C028	White rubber
SN29	A29	NGB26-0037353-0001.C029	Gray plastic
SN30	A30	NGB26-0037353-0001.C030	Black plastic
SN31	A31	NGB26-0037353-0001.C031	Brown rubber ring
SN32	A32	NGB26-0037353-0001.C032	Black rubber
SN33	A33	NGB26-0037353-0001.C033	Black plastic
SN34	A34	NGB26-0037353-0001.C034	Silvery metal
SN35	A35	NGB26-0037353-0001.C035	Black solid adhesive
SN36	A36	NGB26-0037353-0001.C036	Gray solid adhesive
SN37	A37.1☆	NGB26-0037353-0001.C037.C001	Black powder (A37 improved sample submitted by 2026-6-1)
SN38	A38	NGB26-0037353-0001.C038	Silvery metal base
SN39	A39	NGB26-0037353-0001.C039	Black rectifier bridge body
SN40	A40	NGB26-0037353-0001.C040	Black diode body
SN41	A41	NGB26-0037353-0001.C041	Black diode body
SN42	A42	NGB26-0037353-0001.C042	Black audion body
SN43	A43	NGB26-0037353-0001.C043	Black diode body
SN44	A44	NGB26-0037353-0001.C044	Yellow resistor body
SN45	A45	NGB26-0037353-0001.C045	Blue capacitor body
SN46	A46	NGB26-0037353-0001.C046	Black diode body

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

SN ID	Sample No.	SGS Sample ID	Description
SN47	A47	NGB26-0037353-0001.C047	Black plastic shell
SN48	A48	NGB26-0037353-0001.C048	Black rubber
SN49	A49	NGB26-0037353-0001.C049	Black plastic
SN50	A50	NGB26-0037353-0001.C050	Black rubber
SN51	A51	NGB26-0037353-0001.C051	Black plastic
SN52	A52	NGB26-0037353-0001.C052	Yellow solid adhesive
SN53	A53	NGB26-0037353-0001.C053	Yellow plastic shell
SN54	A54	NGB26-0037353-0001.C054	Blue solid adhesive
SN55	A55	NGB26-0037353-0001.C055	Blue plastic shell
SN56	A56	NGB26-0037353-0001.C056	Cyan plastic
SN57	A57	NGB26-0037353-0001.C057	Yellow plastic
SN58	A58	NGB26-0037353-0001.C058	Black coating
SN59	A59	NGB26-0037353-0001.C059	Green coating
SN60	A60	NGB26-0037353-0001.C060	Green coating
SN61	A61	NGB26-0037353-0001.C061	Green PCB body
SN62	A62.1	NGB26-0037353-0001.C062.C001	Silvery metal soldering tin (A62 improved sample submitted by 2026-6-1)
SN63	A63	NGB26-0037353-0001.C063	Silvery metal
SN64	A64	NGB26-0037353-0001.C064	Black PCB body
SN65	A65.1	NGB26-0037353-0001.C065.C001	Silvery metal soldering tin (A65 improved sample submitted by 2026-6-1)
SN66	A66	NGB26-0037353-0001.C066	Yellow resistor body
SN67	A67	NGB26-0037353-0001.C067	Silvery metal
SN68	A68	NGB26-0037353-0001.C068	Black plastic
SN69	A69	NGB26-0037353-0001.C069	Yellow plastic adhesive tape
SN70	A70	NGB26-0037353-0001.C070	Black plastic
SN71	A71	NGB26-0037353-0001.C071	Yellow plastic
SN72	A72	NGB26-0037353-0001.C072	Black plastic shell
SN73	A73	NGB26-0037353-0001.C073	Black plastic
SN74	A74	NGB26-0037353-0001.C074	Silvery metal
SN75	A75	NGB26-0037353-0001.C075	Copper-colored metal
SN76	A76	NGB26-0037353-0001.C076	Black diode body
SN77	A77	NGB26-0037353-0001.C077	Black diode body
SN78	A78	NGB26-0037353-0001.C078	Black diode body
SN79	A79	NGB26-0037353-0001.C079	Black diode body
SN80	A80	NGB26-0037353-0001.C080	Black audion body
SN81	A81	NGB26-0037353-0001.C081	Black audion body
SN82	A82	NGB26-0037353-0001.C082	Green PCB body
SN83	A83	NGB26-0037353-0001.C083	Silvery metal soldering tin
SN84	A84	NGB26-0037353-0001.C084	Black rectifier bridge body
SN85	A85	NGB26-0037353-0001.C085	Black solid adhesive
SN86	B1	NGB26-0037353-0002.C001	Silvery metal cover
SN87	B2	NGB26-0037353-0002.C002	Red plastic
SN88	B3	NGB26-0037353-0002.C003	Green PCB body
SN89	B4.1	NGB26-0037353-0002.C004.C001	Silvery metal soldering tin (B4 improved sample submitted by 2026-6-1)
SN90	B5	NGB26-0037353-0002.C005	Silvery metal
SN91	B6	NGB26-0037353-0002.C006	Black PCB body
SN92	B7	NGB26-0037353-0002.C007	Silvery metal soldering tin

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

SN ID	Sample No.	SGS Sample ID	Description
SN93	B8	NGB26-0037353-0002.C008	Black diode body
SN94	B9	NGB26-0037353-0002.C009	Black rectifier bridge body
SN95	B10	NGB26-0037353-0002.C010	Black diode body
SN96	B11	NGB26-0037353-0002.C011	Black audion body
SN97	B12	NGB26-0037353-0002.C012	Black diode body
SN98	B13	NGB26-0037353-0002.C013	Green PCB body
SN99	B14	NGB26-0037353-0002.C014	Silvery metal soldering tin
SN100	B15	NGB26-0037353-0002.C015	Black diode body
SN101	B16	NGB26-0037353-0002.C016	Black audion body
SN102	B17	NGB26-0037353-0002.C017	Black audion body
SN103	C1	NGB26-0037353-0003.C001	Green PCB body
SN104	C2	NGB26-0037353-0003.C002	Silvery metal soldering tin

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Verification Result(s):

In accordance with the result of material risk assessment, the following disjointed parts in the submitted sample have been verified. (Unless otherwise specified, the unit is mg/kg).

Test Item(s)	A1	A2	A3	A4	A5	A6	A7	A8
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	ND	BL	ND	BL	BL	BL	BL
PBB	---	---	BL	---	BL	BL	BL	BL
PBDE	---	---	BL	---	BL	BL	BL	BL
DEHP	---	---	ND	---	ND	BL	BL	BL
BBP	---	---	ND	---	ND	BL	BL	BL
DBP	---	---	ND	---	ND	BL	BL	BL
DIBP	---	---	ND	---	ND	BL	BL	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A9	A10	A11	A12	A13	A14	A15	A16
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	BL	---	BL	BL	BL	ND	---	BL
PBDE	BL	---	BL	BL	BL	ND	---	BL
DEHP	BL	---	BL	BL	BL	BL	---	BL
BBP	BL	---	BL	BL	BL	BL	---	BL
DBP	BL	---	BL	BL	BL	BL	---	BL
DIBP	BL	---	BL	BL	BL	BL	---	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A17	A18	A19	A20	A21	A22	A23	A24.1
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	BL	BL	BL	BL	BL	BL	ND	---
PBDE	BL	BL	BL	BL	BL	BL	ND	---
DEHP	BL	BL	BL	ND	ND	ND	BL	---
BBP	BL	BL	BL	ND	ND	ND	BL	---
DBP	BL	BL	BL	ND	ND	ND	BL	---
DIBP	BL	BL	BL	ND	ND	ND	BL	---
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A25	A26	A27	A28	A29	A30	A31	A32
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	ND	BL	BL	BL	BL	BL	BL

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Test Item(s)	A25	A26	A27	A28	A29	A30	A31	A32
PBB	---	---	BL	BL	BL	BL	BL	BL
PBDE	---	---	BL	BL	BL	BL	BL	BL
DEHP	---	---	BL	BL	BL	BL	ND	BL
BBP	---	---	BL	BL	BL	BL	ND	BL
DBP	---	---	BL	BL	BL	BL	ND	BL
DIBP	---	---	BL	BL	BL	BL	ND	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A33	A34	A35	A36	A37.1☆	A38	A39	A40
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	ND	BL	BL	BL
PBB	BL	---	BL	BL	BL	---	ND	BL
PBDE	BL	---	BL	BL	BL	---	ND	BL
DEHP	BL	---	BL	BL	ND	---	BL	BL
BBP	BL	---	BL	BL	ND	---	BL	BL
DBP	BL	---	BL	BL	ND	---	BL	BL
DIBP	BL	---	BL	BL	ND	---	BL	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A41	A42	A43	A44	A45	A46	A47	A48
Pb	26045▲	BL	OL▲	BL	BL	OL▲	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	BL	BL	BL	BL	BL	BL	BL	BL
PBDE	BL	BL	BL	BL	BL	BL	BL	BL
DEHP	BL	BL	BL	BL	BL	ND	BL	BL
BBP	BL	BL	BL	BL	BL	ND	BL	BL
DBP	BL	BL	BL	BL	BL	ND	BL	BL
DIBP	BL	BL	BL	BL	BL	ND	BL	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A49	A50	A51	A52	A53	A54	A55	A56
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	BL	BL	BL	ND	ND	ND	ND	ND
PBDE	BL	BL	BL	ND	ND	ND	ND	ND
DEHP	ND	ND	BL	BL	BL	BL	BL	BL
BBP	ND	ND	BL	BL	BL	BL	BL	BL
DBP	ND	ND	BL	BL	BL	BL	BL	BL
DIBP	ND	ND	BL	BL	BL	BL	BL	BL

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab. Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Test Item(s)	A49	A50	A51	A52	A53	A54	A55	A56
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A57	A58	A59	A60	A61	A62.1	A63	A64
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	ND	BL	BL	BL	ND	---	---	BL
PBDE	ND	BL	BL	BL	ND	---	---	BL
DEHP	BL	ND	ND	ND	BL	---	---	BL
BBP	BL	ND	ND	ND	BL	---	---	BL
DBP	BL	ND	ND	ND	BL	---	---	BL
DIBP	BL	ND	ND	ND	BL	---	---	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A65.1	A66	A67	A68	A69	A70	A71	A72
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	---	BL	---	BL	BL	BL	BL	ND
PBDE	---	BL	---	BL	BL	BL	BL	ND
DEHP	---	BL	---	BL	ND	BL	BL	BL
BBP	---	BL	---	BL	ND	BL	BL	BL
DBP	---	BL	---	BL	ND	BL	BL	BL
DIBP	---	BL	---	BL	ND	BL	BL	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A73	A74	A75	A76	A77	A78	A79	A80
Pb	BL	BL	BL	BL	BL	BL	BL	OL▲
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	ND	---	---	BL	BL	BL	BL	BL
PBDE	ND	---	---	BL	BL	BL	BL	BL
DEHP	BL	---	---	ND	BL	ND	ND	BL
BBP	BL	---	---	ND	BL	ND	ND	BL
DBP	BL	---	---	ND	BL	ND	ND	BL
DIBP	BL	---	---	ND	BL	ND	ND	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A81	A82	A83	A84	A85	B1	B2	B3
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab. Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Test Item(s)	A81	A82	A83	A84	A85	B1	B2	B3
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	BL	ND	---	BL	BL	---	BL	ND
PBDE	BL	ND	---	BL	BL	---	BL	ND
DEHP	BL	BL	---	BL	BL	---	ND	BL
BBP	BL	BL	---	BL	BL	---	ND	BL
DBP	BL	BL	---	BL	BL	---	ND	BL
DIBP	BL	BL	---	BL	BL	---	ND	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	B4.1	B5	B6	B7	B8	B9	B10	B11
Pb	BL	BL	BL	BL	BL	BL	19174▲	OL▲
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	---	---	ND	---	BL	BL	BL	BL
PBDE	---	---	ND	---	BL	BL	BL	BL
DEHP	---	---	BL	---	ND	ND	ND	BL
BBP	---	---	BL	---	ND	ND	ND	BL
DBP	---	---	BL	---	ND	ND	ND	BL
DIBP	---	---	BL	---	ND	ND	ND	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	B12	B13	B14	B15	B16	B17	C1	C2
Pb	BL	BL	BL	BL	OL▲	OL▲	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	BL	ND	---	BL	BL	ND	ND	---
PBDE	BL	ND	---	BL	BL	ND	ND	---
DEHP	BL	BL	---	BL	BL	BL	BL	---
BBP	BL	BL	---	BL	BL	BL	BL	---
DBP	BL	BL	---	BL	BL	BL	BL	---
DIBP	BL	BL	---	BL	BL	BL	BL	---
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Notes:

(1) Interpretation of screening results by X-ray fluorescence spectrometry (XRF):

(a) Screening limits in mg/kg for regulated elements in various matrices according to IEC 62321-3-1:2013 Annex A as below table.

Element	Polymers	Metals	Composite Materials
Cd	BL≤(70-3σ)<X<(130+3σ)≤OL	BL≤(70-3σ)<X<(130+3σ)≤OL	LOD<X<(150+3σ)≤OL
Pb	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(500-3σ)<X<(1500+3σ)≤OL
Hg	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(500-3σ)<X<(1500+3σ)≤OL
Br	BL ≤ (300-3σ)< X	Not applicable	BL ≤ (250-3σ)< X
Cr	BL ≤ (700-3σ)< X	BL ≤ (700-3σ)< X	BL ≤ (500-3σ)< X

(b) If the maximum allowed level restricts PBB/PBDE and Cr(VI) rather than Br and Cr, the exceptions are the XRF determinations of Br and Cr. If the quantitative results for the elements Br and/or Cr are higher than the limit (for Br calculated based on the stoichiometry of Br in the most common congeners of PBB/PBDE), the sample is “inconclusive”.

(c) Results are obtained by EDXRF for primary screening, LOD = Limit of Detection, BL = Below Limit, OL= Over Limit, IN (The symbol X marks the region)=Inconclusive, where further investigation is necessary, and further chemical testing by ICP-OES (for Cd, Pb, Hg), UV-Vis (for Cr(VI)) and GC-MS (for PBB/PBDE) are recommended to be performed.

(d) The EDXRF screening test for elements – The reading may be different to the actual content in the sample be of non-uniformity composition.

(2) Screening results of Phthalates (PHTH) below the limits are shown as "BL". Further chemical testing by GC-MS is to be performed if the results exceed limits.

Test Items	CAS No.
Bis(2-ethylhexyl) phthalate (DEHP)	117-81-7
Butyl benzyl phthalate (BBP)	85-68-7
Dibutyl phthalate (DBP)	84-74-2
Diisobutyl phthalate (DIBP)	84-69-5

(3) Interpretation of results by chemical tests:

(a) mg/kg = 0.0001%, MDL=Method detection Limit, ND = Not Detected (<MDL), --- = Not Applicable.

(b) Unit and MDL in wet chemical test

Test Items	Pb	Hg	Cd	DEHP	BBP	DBP	DIBP
Unit	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
MDL	10	10	10	100	100	100	100

The MDL for single compound of PBB and PBDE is 100 mg/kg,
MDL of Cr(VI) for polymer, composite and leather sample is 10 mg/kg.
MDL of Cr(VI) for metal sample is 0.10 μg/cm^2.

(c) ▼ =Metal sample

a. The sample is positive for Cr(VI) if the Cr(VI) concentration is greater than 0.13 μg/cm^2. The sample coating is considered to contain Cr(VI).

b. The sample is negative for Cr(VI) if Cr(VI) is ND (concentration less than 0.10 μg/cm^2). The coating is considered a non-Cr(VI) based coating

c. The result between 0.10 μg/cm^2 and 0.13 μg/cm^2 is considered to be inconclusive-unavoidable coating variations may influence the determination

Information on storage conditions and production date of the tested sample is unavailable and thus Cr(VI) results represent status of the sample at the time of testing.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

(4) Restricted substances and maximum concentration values tolerated by weight in homogeneous materials under RoHS Directive: Cd: 0.01%, Pb/Hg/Cr(VI)/PBB/PBDE/DEHP/BBP/DBP/DIBP: 0.1%. The limit is quoted from RoHS Directive (EU) 2015/863.

(5) IEC 62321 series is equivalent to EN 62321 series.

(6) ☆=Based on the declaration submitted by the applicant, A37.1 is raw material of A37, and its results for support the results of A37, The applicant will take the responsibility of all discrepancy and risk.

(7) ▲=According to the declaration from the client, Lead (Pb) in sample A41, A43, A46, A80, B10, B11, B16, B17 are exempted by EU RoHS directive 2011/65/EU based on |ANNEX III 7(c)-I|: Electrical and electronic components containing lead in a glass or ceramic other than dielectric ceramic in capacitors, e.g. piezoelectronic devices, or in a glass or ceramic matrix compound.
More information about exemption can be found via the following link:
https://rohs.sgsonline.com.cn/PDFLinks/en/RSTS-TP-037%20RoHS%20Exemption%20%28EN%29.pdf

(8) According to the declaration from applicant, the materials of other parts in Model mentioned in Tested Extended Model No. are the same as those in Model " SG* ", and the results of Model " SG* " for support the results of other parts in mentioned in Tested Extended Model No.. The applicant will take the responsibility of all discrepancy and risk.

(9) According to the declaration from applicant, the materials of Model “SG*” are the same as those in Model mentioned in Client Ref. Information and its results for support the results of Model mentioned in Client Ref. Information. The applicant will take the responsibility of all discrepancy and risk.

Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (*w*=0) stated in ILAC-G8:09/2019.


通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab. Branch


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区，5区 sgs.china@sgs.com


Member of the SGS Group (SGS SA)


Sample photos:


















通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab. (China)


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

















通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

















通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com

















通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com





SG1000












通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com






SG500





SGS authenticate the photo on original report only
*** End of Report ***

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com