Verification Report

No.: NGBEC26003735201 **Date:** Jun 08, 2026

Client Name: SOLENSO ELECTRONIC MATERIALS CO.,LTD.

Client Address: 4F.,NO.56,ZILI 5TH ST.,ZHONGLI DIST.,TAOYUAN CITY 320,TAIWAN,CHINA

Sample Name: Data Transfer Unit

Tested Basic Model No.: DTU-SLV

The above sample(s) and information were provided by the client.

SGS Job No.: NBP26-003810

Sample Receiving Date: May 11, 2026

Verification Period: May 11, 2026 ~ Jun 05, 2026

Verification Requested: With reference to RoHS Directive (EU) 2015/863 amending 2011/65/EU.

Verification Method(s): Please refer to next page(s).

Verification Result(s): Please refer to next page(s).

Test Result Summary:

Test Items	Conclusion
EU RoHS Directive (EU) 2015/863 amending Annex II to Directive 2011/65/EU - Lead, Mercury, Cadmium, Hexavalent chromium, Polybrominated biphenyls (PBB), Polybrominated diphenyl ethers (PBDE), Bis(2-ethylhexyl) phthalate (DEHP), Butyl benzyl phthalate (BBP), Dibutyl phthalate (DBP) and Diisobutyl phthalate (DIBP)	Pass

Signed for and on behalf of
SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Hedy Hu
Approved Signatory


Scan to see the report

1505DB55

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，006幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Photo of Submitted Sample



DTU-SLV

Verification Method(s):

1. With reference to IEC 62321-2:2021, disassembly and disjointment were performed for the submitted samples.
2. With reference to IEC 62321-1:2013, tests were performed for the samples indicated by the photos in this report.
   (1) With reference to IEC 62321-3-1:2013, screening by EDXRF spectroscopy.
   (2) Wet chemical test method: With reference to IEC 62321-4:2013+A1:2017, IEC62321-5:2013, IEC 62321-7-1:2015, IEC 62321-7-2:2017, IEC 62321-12:2023, IEC 62321-6:2015 and IEC62321-8:2017 , analyzed by ICP-OES,UV-Vis and GC-MS.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab (China)

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区，5区 sgs.china@sgs.com

Verification Part Description:

SN ID	Sample No.	SGS Sample ID	Description
SN1	A1	NGB26-0037352-0001.C001	White plastic
SN2	A2	NGB26-0037352-0001.C002	White plastic
SN3	A3	NGB26-0037352-0001.C003	Golden metal
SN4	A4	NGB26-0037352-0001.C004	White plastic
SN5	A5	NGB26-0037352-0001.C005	Silvery metal
SN6	A6.1	NGB26-0037352-0001.C006.C001	Black foam (A6 improved sample submitted by 2026-5-29)
SN7	A7	NGB26-0037352-0001.C007	Golden metal
SN8	A8	NGB26-0037352-0001.C008	Green PCB body
SN9	A9.1	NGB26-0037352-0001.C009.C001	Silvery metal soldering tin (A9 improved sample submitted by 2026-5-29)
SN10	A10	NGB26-0037352-0001.C010	Golden metal
SN11	A11	NGB26-0037352-0001.C011	Blue rubber ring
SN12	A12	NGB26-0037352-0001.C012	Brown plastic sheath
SN13	A13	NGB26-0037352-0001.C013	White plastic jacket
SN14	A14	NGB26-0037352-0001.C014	White plastic shell
SN15	A15.1	NGB26-0037352-0001.C015.C001	Silvery metal screw (A15 improved sample submitted by 2026-5-29)
SN16	A16	NGB26-0037352-0001.C016	Transparent plastic
SN17	A17	NGB26-0037352-0001.C017	Beige plastic
SN18	A18	NGB26-0037352-0001.C018	White plastic
SN19	A19	NGB26-0037352-0001.C019	White solid adhesive
SN20	A20	NGB26-0037352-0001.C020	Beige plastic
SN21	A21	NGB26-0037352-0001.C021	Black diode body
SN22	A22	NGB26-0037352-0001.C022	Black diode body
SN23	A23	NGB26-0037352-0001.C023	Green resistor body
SN24	A24	NGB26-0037352-0001.C024	Black plastic sheath
SN25	A25	NGB26-0037352-0001.C025	Semitransparent plastic jacket
SN26	A26	NGB26-0037352-0001.C026	Silvery metal
SN27	A27	NGB26-0037352-0001.C027	Black plastic
SN28	A28	NGB26-0037352-0001.C028	Black plastic
SN29	A29	NGB26-0037352-0001.C029	Silvery metal
SN30	A30	NGB26-0037352-0001.C030	Green plastic
SN31	A31	NGB26-0037352-0001.C031	Silvery metal
SN32	A32	NGB26-0037352-0001.C032	Gray plastic
SN33	A33	NGB26-0037352-0001.C033	Silvery metal
SN34	A34	NGB26-0037352-0001.C034	Silvery metal
SN35	A35	NGB26-0037352-0001.C035	Silvery metal
SN36	A36	NGB26-0037352-0001.C036	Beige plastic
SN37	A37	NGB26-0037352-0001.C037	Colourful plastic label
SN38	A38	NGB26-0037352-0001.C038	Silvery metal cover
SN39	A39	NGB26-0037352-0001.C039	Black PCB body
SN40	A40	NGB26-0037352-0001.C040	Silvery metal soldering tin
SN41	A41	NGB26-0037352-0001.C041	Green PCB body
SN42	A42	NGB26-0037352-0001.C042	Silvery metal soldering tin
SN43	A43	NGB26-0037352-0001.C043	Silvery metal cover
SN44	A44	NGB26-0037352-0001.C044	Black PCB body
SN45	A45	NGB26-0037352-0001.C045	Silvery metal soldering tin

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Laboratory

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

SN ID	Sample No.	SGS Sample ID	Description
SN46	A46	NGB26-0037352-0001.C046	Green PCB body
SN47	A47	NGB26-0037352-0001.C047	Silvery metal soldering tin

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Verification Result(s):

In accordance with the result of material risk assessment, the following disjointed parts in the submitted sample have been verified. (Unless otherwise specified, the unit is mg/kg).

Test Item(s)	A1	A2	A3	A4	A5	A6.1	A7	A8
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	BL	BL	---	BL	---	ND	---	BL
PBDE	BL	BL	---	BL	---	ND	---	BL
DEHP	BL	BL	---	BL	---	ND	---	BL
BBP	BL	BL	---	BL	---	ND	---	BL
DBP	BL	BL	---	BL	---	ND	---	BL
DIBP	BL	BL	---	BL	---	ND	---	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A9.1	A10	A11	A12	A13	A14	A15.1	A16
Pb	BL	32540▲	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	ND	BL
PBB	---	---	BL	BL	BL	BL	---	BL
PBDE	---	---	BL	BL	BL	BL	---	BL
DEHP	---	---	ND	ND	ND	BL	---	BL
BBP	---	---	ND	ND	ND	BL	---	BL
DBP	---	---	ND	ND	ND	BL	---	BL
DIBP	---	---	ND	ND	ND	BL	---	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A17	A18	A19	A20	A21	A22	A23	A24
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	ND	BL
PBB	BL	BL	BL	BL	BL	BL	BL	BL
PBDE	BL	BL	BL	BL	BL	BL	BL	BL
DEHP	BL	BL	BL	BL	BL	BL	BL	BL
BBP	BL	BL	BL	BL	BL	BL	BL	BL
DBP	BL	BL	BL	BL	BL	BL	BL	BL
DIBP	BL	BL	BL	BL	BL	BL	BL	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A25	A26	A27	A28	A29	A30	A31	A32
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Test Item(s)	A25	A26	A27	A28	A29	A30	A31	A32
PBB	BL	---	BL	ND	---	BL	---	ND
PBDE	BL	---	BL	ND	---	BL	---	ND
DEHP	BL	---	ND	BL	---	BL	---	BL
BBP	BL	---	ND	BL	---	BL	---	BL
DBP	BL	---	ND	BL	---	BL	---	BL
DIBP	BL	---	ND	BL	---	BL	---	BL
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A33	A34	A35	A36	A37	A38	A39	A40
Pb	BL	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL	BL
PBB	---	---	---	BL	BL	---	ND	---
PBDE	---	---	---	BL	BL	---	ND	---
DEHP	---	---	---	ND	ND	---	BL	---
BBP	---	---	---	ND	ND	---	BL	---
DBP	---	---	---	ND	ND	---	BL	---
DIBP	---	---	---	ND	ND	---	BL	---
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS	PASS

Test Item(s)	A41	A42	A43	A44	A45	A46	A47
Pb	BL	BL	BL	BL	BL	BL	BL
Hg	BL	BL	BL	BL	BL	BL	BL
Cd	BL	BL	BL	BL	BL	BL	BL
Cr(VI)▼	BL	BL	BL	BL	BL	BL	BL
PBB	ND	---	---	ND	---	ND	---
PBDE	ND	---	---	ND	---	ND	---
DEHP	BL	---	---	BL	---	BL	---
BBP	BL	---	---	BL	---	BL	---
DBP	BL	---	---	BL	---	BL	---
DIBP	BL	---	---	BL	---	BL	---
Conclusion	PASS	PASS	PASS	PASS	PASS	PASS	PASS

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层2区，008幢7号楼2层2区、5区 sgs.china@sgs.com

Notes:

(1) Interpretation of screening results by X-ray fluorescence spectrometry (XRF):

(a) Screening limits in mg/kg for regulated elements in various matrices according to IEC 62321-3-1:2013 Annex A as below table.

Element	Polymers	Metals	Composite Materials
Cd	BL≤(70-3σ)<X<(130+3σ)≤OL	BL≤(70-3σ)<X<(130+3σ)≤OL	LOD<X<(150+3σ)≤OL
Pb	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(500-3σ)<X<(1500+3σ)≤OL
Hg	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(700-3σ)<X<(1300+3σ)≤OL	BL≤(500-3σ)<X<(1500+3σ)≤OL
Br	BL ≤ (300-3σ)< X	Not applicable	BL ≤ (250-3σ)< X
Cr	BL ≤ (700-3σ)< X	BL ≤ (700-3σ)< X	BL ≤ (500-3σ)< X

(b) If the maximum allowed level restricts PBB/PBDE and Cr(VI) rather than Br and Cr, the exceptions are the XRF determinations of Br and Cr. If the quantitative results for the elements Br and/or Cr are higher than the limit (for Br calculated based on the stoichiometry of Br in the most common congeners of PBB/PBDE), the sample is “inconclusive”.

(c) Results are obtained by EDXRF for primary screening, LOD = Limit of Detection, BL = Below Limit, OL= Over Limit, IN (The symbol X marks the region)=Inconclusive, where further investigation is necessary, and further chemical testing by ICP-OES (for Cd, Pb, Hg), UV-Vis (for Cr(VI)) and GC-MS (for PBB/PBDE) are recommended to be performed.

(d) The EDXRF screening test for elements – The reading may be different to the actual content in the sample be of non-uniformity composition.

(2) Screening results of Phthalates (PHTH) below the limits are shown as "BL". Further chemical testing by GC-MS is to be performed if the results exceed limits.

Test Items	CAS No.
Bis(2-ethylhexyl) phthalate (DEHP)	117-81-7
Butyl benzyl phthalate (BBP)	85-68-7
Dibutyl phthalate (DBP)	84-74-2
Diisobutyl phthalate (DIBP)	84-69-5

(3) Interpretation of results by chemical tests:

(a) mg/kg = 0.0001%, MDL=Method detection Limit, ND = Not Detected (<MDL), --- = Not Applicable.

(b) Unit and MDL in wet chemical test

Test Items	Pb	Hg	Cd	DEHP	BBP	DBP	DIBP
Unit	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg	mg/kg
MDL	10	10	10	100	100	100	100

The MDL for single compound of PBB and PBDE is 100 mg/kg,
MDL of Cr(VI) for polymer, composite and leather sample is 10 mg/kg.
MDL of Cr(VI) for metal sample is 0.10 μg/cm^2.

(c) ▼ =Metal sample

a. The sample is positive for Cr(VI) if the Cr(VI) concentration is greater than 0.13 μg/cm^2. The sample coating is considered to contain Cr(VI).

b. The sample is negative for Cr(VI) if Cr(VI) is ND (concentration less than 0.10 μg/cm^2). The coating is considered a non-Cr(VI) based coating

c. The result between 0.10 μg/cm^2 and 0.13 μg/cm^2 is considered to be inconclusive-unavoidable coating variations may influence the determination

Information on storage conditions and production date of the tested sample is unavailable and thus Cr(VI) results represent status of the sample at the time of testing.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd.

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

(4) Restricted substances and maximum concentration values tolerated by weight in homogeneous materials under RoHS Directive: Cd: 0.01%, Pb/Hg/Cr(VI)/PBB/PBDE/DEHP/BBP/DBP/DIBP: 0.1%. The limit is quoted from RoHS Directive (EU) 2015/863.

(5) IEC 62321 series is equivalent to EN 62321 series.

(6) ▲=According to the declaration from the client, Lead (Pb) in sample A10 is exempted by EU RoHS directive 2011/65/EU based on |ANNEX III 6(c)|: Copper alloy containing up to 4 % lead by weight.
More information about exemption can be found via the following link:
https://rohs.sgsonline.com.cn/PDFLinks/en/RSTS-TP-037%20RoHS%20Exemption%20%28EN%29.pdf


Unless otherwise stated, the decision rule for conformity reporting is based on Binary Statement for Simple Acceptance Rule (*w*=0) stated in ILAC-G8:09/2019.

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch


Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com


Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国・浙江・宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com


Sample photos:





DTU-SLV












通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com



SGS authenticate the photo on original report only

*** End of Report ***

Unless otherwise agreed in writing, this document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at https://www.sgs.com/en/Terms-and-Conditions. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.
Attention: To check the authenticity of testing /inspection report & certificate, please contact us at telephone: (86-755) 8307 1443, or email: CN.Doccheck@sgs.com

通标标准技术服务（宁波）有限公司 检验检测专用章 Inspection & Testing Services
SGS-CSTC Standards Technical Services (Ningbo) Co., Ltd. Central Chemical Lab Branch
Unit 6, 1/F., & Unit 2 & Unit 5, 2/F., Building 7 / 1/F., & Unit 2, 4/F., Building 5 / Unit 2, 1/F., & 2/F. to 5/F., Building 4 / Unit 2, 1/F., Building 3 / 4/F., Building 1, No. 1177 Lingyun Road, Meixu Subdistrict, Hi-Tech Zone, Ningbo, Zhejiang, China. www.sgsgroup.com.cn
中国·浙江·宁波市高新区梅墟街道凌云路1177号007幢1号楼4层，003幢3号楼1层2区，009幢4号楼1层2区，009幢4号楼2-5层，006幢5号楼1层，004幢5号楼4层2区，008幢7号楼1层4区，008幢7号楼2层2区、5区 sgs.china@sgs.com